

## TRAFFIC

Pedestrians do not have the right-of-way in the shipyard and must yield to all vehicle and crane movement.

**BEWARE OF CRANE MOVEMENT AND SUSPENDED LOADS.** No one shall travel under a suspended load and should keep a safe distance away. For example, if the load is 25 feet in the air, your distance away from the load should also equal 25 feet. All persons must remain back from suspended loads and take direction from the attending riggers

The speed limit in the yard is 5 mph.

**There is no running on the yard.**

Metal Trades, Inc. facilities include its shipyard at 4194 Hwy 165, Yorges Island, SC plus certain other building and facilities located in the surrounding area. MTI builds, and repairs both military and commercial vessels and heavy steel manufacturing.

For your safety, MTI requires that everyone entering the shipyard or other production locations wears the minimum Personal Protective Equipment (PPE) identified in this brochure.

## EMERGENCY NUMBERS

<u>Incident Type</u>	<u>Landline</u>	<u>Cell Phone</u>
Fire or Medical	911	843-637-5231
Spill Reporting	x5138	843-901-3324
Environmental (>300GA.)		843-797-0402

## GENERAL INFORMATION NUMBERS

### Information Type

Environmental	843-901-3324
Fire Department	843-889-8874
Maintenance	843-693-4046
Medical	843-637-5231
Safety	843-637-5231
Security	843-889-5145
Operations	843-670-0900



# Basic Safety Requirements

WE ENSURE A SAFE WORKPLACE FOR ALL.

Welcome to METAL TRADES, INCORPORATED (MTI). To ensure a safe and enjoyable visit to our facility, we ask that you review the safety information contained in this brochure. If you have any questions, please ask your sponsor or contact the, MTI Safety office at 843-889-5138

## VISITORS & VENDORS

WHEN ARRIVING AT MTI THE FOLLOWING WILL BE REQUIRED:

- HARD HATS
- SAFETY GLASSES
- HEARING PROTECTON

## Minimum PPE for transiting the shipyard

### CLOTHING

The minimum clothing requirements while visiting or transiting the shipyard are:

- Shirts/Blouses
  - Must cover the entire torso;
  - Must have at least short sleeves. (Tank tops and sleeveless shirts are not permitted.)
- Trousers/Pants must be full length with no portion of the leg exposed.
- Skirts/Dresses as business appropriate and only while transiting between offices.

### FOOT PROTECTION

All persons entering the shipyard must wear sturdy all-leather shoes or boots that cover the entire foot and have a well defined heel. The heel must be at least ¼" and no more than 1¾". It is prohibited to wear tennis shoes, sneakers, shoes with uppers containing any man-made material, cloth shoes, light-weight leather shoes, and high-heeled shoes in the shipyard. Open-toe shoes, sandals, and slipper-type footwear may not be worn in the shipyard at any time.



### HEAD PROTECTION

Hard hats must be worn in all production areas. Hard hats must meet the ANSI Z89.1 Standard, be fire retardant, and not conduct electricity. (Cowboy-type hard hats are not allowed.)



### EYE PROTECTION

Only safety glasses that meet the ANSI Z87.1 standard are acceptable and must be worn at all times in the shipyard. Dark lenses that hide the eyes are not allowed on board any vessel. DO NOT STARE AT ANY WELDING ARC since prolonged exposure can cause injury to your eyes.



### HEARING PROTECTION

Hearing must be protected at all times by wearing suitable ear plugs or ear muffs in noise hazard areas. The blast cells at the south end of the yard require double hearing protection.



**CONTRACTORS** are required to provide their own hard hats, safety glasses, hearing protection and other required PPE.

